



参数	工作温度 (°C)	工作相对湿	储温度 (°C)	存储相对湿度 (%)	引脚焊接温度 (max/°C)
最小	10	-	-20	-	-
最大	30	75	70	90	250(10Sec.)




* D -
* P -
FS -



808nm P-I-V



808nm



08BULT

